

# 1. About the product(C80/82)

Thank you for using EZ-CIS (Easy-Continuing inking-sysytem)  
There is no need to remove anything from the original printer for this product. It uses ink that are high quality. This product is suitable for customers that produce a large quantity of color photos.


For example, Advertestment company and people who loves taking photos. The quality of the these photos will be at the same level as the photo films.

## 2. Package Tabulates


Ink Supply Main System  
Wire Clipper  
How To Install

1 piece  
1 piece  
1 piece


## 3. Accessory Explanation



Ink Supply Main System



## 4. Setup



<Diagram 1>


A. See how you insert cartridge from your printer's manual information booklet. Insert these cartridge in the same way. Make sure the ink tubes are parallel to the printer(Diagram 1).



<Diagram 3>




<Diagram 4>



<Diagram 2>

B. Insert the tubes into the position that shows in diagram 2 and diagram 3, please notify:

1. Insert the ink tubes exactly as shown in diagram 3
2. Move the cartilage car to the end of the right side, so the tubes has the right length



<Diagram 5>

C. Remove the spring, and keep it (Diagram 5).

1. This system won't effect other process and you don't have to do any other extra process to use this system
2. When using our system for the first time, make sure you switch on the power for the EZ-CIS system
3. Before Printing for the first time, make sure that you clean the pin head 2-3 times, otherwise it might effect the quality
4. When placing the EZ-CIS system, place it at the same height level to the printer, at most 5cm. If u put it higher the pin will have too much ink, therefor smuggling may occur, if you put it too low, the ink may not travel to the oin head.
5. Please avoid, putting the EZ-CIS system where there are; strong light, sun light, dust, high or low temperatures or places where it might be unstable.
6. When changing places for the EZ-CIS system, make sure that you move both the EZ-CIS system and the printer.
7. Don't re-setup the system, it might effect the quality
8. Make sure you use the ink from the same company
9. When the is an ink warning( Low ink), refill as soon as possible.
10. When the quality decreases, check the oin head, it may need cleaning